

INVESTIGATION AND REPAIR OF A FAILED OLYMPIC POOL



FIGURE 1 VERY LARGE BUBBLE IN THE FLOOR LINER WHICH GREW OUT OF THE WATER DURING THE OPERATION OF THE POOL

From the beginning of the operation of the Olympic Pool in Tennessee there were signs of trouble. The water in the pool would not clear up, the pool liner had bubbles which appeared to grow over time, and the pool floor needed constant vacuuming. Initial thoughts by the contractor who constructed the pool was that filtration plumbing, which was installed below the pool floor, contained a significant amount of construction debris which was making its way into the pool. As the pool continued to operate, the blisters in the liner grew, which was speculated to be the result of a high groundwater table. Eventually one of these bubbles became so large that it rose above the water surface. To deflate this now very significant liner bubble, it was punctured spewing soil and water (see Figure 1).

With all the confusion and various theories on what caused this just constructed Olympic pool to fail, MEA was selected to perform an independent forensic investigation.

From a borehole camera inspection it was discovered that there was a significant fracturing of the sub-floor plumbing. The fracturing was concentrated at the connector of the rise pipe and header (see Figure 2). Also from manometer survey and photographic information it was established that the pool floor and wall had settled. Normally, such pool settlement would not affect the




FIGURE 2 TYPICAL FRACTURING FOUND AT THE RISER/HEADER CONNECTION

